EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	13254	head AND screw AND nut.ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:48
L2	1299	1 and (force).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:49
L3	70	2 and (diamond amorphous carbon nanocrystalline)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:47
L4	7	3 and (sens\$4 detect\$4 transducer measur\$4 gage gauge).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:49
L5	5	4 and (prominence protrusion groove protruberance)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:56
L6	417333	washer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:48
L7	5041	6 and head AND screw AND nut. clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:56
L8	1329	7 and (force).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:49
L9	175	8 and (sens\$4 detect\$4 transducer measur\$4 gage gauge).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:57

10/26/06 11:40:54 AM Page 1

EAST Search History

L10	103	9 and (prominence protrusion groove protruberance)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:51
L11	60	10 and (sleeve)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:51
L12	18	11 and (insulat\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:54
L13	9	"5769581"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:55
L14	3134	screw near3 connection.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:56
L15	140	14 and (head AND nut).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:56
L16	69	15 and (prominence protrusion groove protruberance)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:56
L17	23	16 and (force).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:58
L18	5	17 and (sens\$4 detect\$4 transducer measur\$4 gage gauge).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:58
L19	9	17 and (sens\$4 detect\$4 transducer measur\$4 gage gauge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/26 10:58

10/26/06 11:40:54 AM Page 2

EAST Search History

L20	8	17 and (resistance)	US-PGPUB;	OR	ON	2006/10/26 10:58
			USPAT;			
			USOCR;			
			EPO; JPO;			
			DERWENT			

10/26/06 11:40:54 AM Page 3